

# Index

## A

Adding and Removing Sheets in the Drawing 12-6  
Adding Balloons to the assembly views 11-20  
Adding New Parts or Assemblies to the Current Drawing 10-15  
Adding Notes to the Drawing 11-19  
Adding or Removing the Cross Section Arrows 10-16  
Adding reference datums to the drawing views 11-12  
Adding Tolerances in the Drawing Views 11-14  
Advanced Feature option 8-2  
Advanced Sectioning Options 10-10  
Align 9-4  
Align Coincident 9-5  
Align Offset 9-5  
Align Oriented 9-5  
Align Xsec 10-11  
Area Xsec 10-11  
Assembling Repeated Copies of a Component 9-16  
Assembling the Components 9-7  
Assembly Datum Planes 9-7  
Assembly Modeling 9-2  
ATTRIBUTES menu 3-7  
Autodimensioning in Pro/ENGINEER 2-6  
Automatic 9-3  
Auxiliary View 10-6

## B

Bidirectional Associative Nature of Pro/ENGINEER iii  
Blend 7-8  
Bndry Chain 7-6  
Broken View 10-8

## C

Chamfers 5-11  
Changing the View Name 10-16  
Changing the View Scale 10-16  
Changing the View Type 10-15  
Cleaning Up the Dimensions 11-10

Closed 7-11  
Comparison Relations 8-10  
Constant 8-6  
Converting a Weak Constraint into a Strong Constraint 1-18  
Coord Sys 9-6  
Copy 6-6  
Creating a Protrusion 3-3  
Creating base features 3-2  
Creating Cuts 4-19  
Creating Simplified Representations 9-13  
Creating Sweep feature by selecting a trajectory 7-5  
Creating Tables 12-7  
Creating the Exploded State 9-18  
Creating the Offset Lines 9-20  
Creating the section planes 10-12  
Curve Chain 7-6

## D

Datum Axes 4-11  
Datum Curves 7-13  
Datum Options 4-3  
Datum Planes 4-4  
Datum Planes Created “On The Fly” 4-11  
Datum Points 4-14  
Datums 4-2  
Default 9-7  
Default Datum Planes 4-2  
Deleting a feature 5-16  
Deleting a Pattern 6-5  
Deleting objects 1-22  
Deleting the Drawing Views 10-15  
Dependent 6-8  
Detailed View 10-6  
Difference in working with and without the Intent Manager 1-18  
Dimensional Tolerances 11-15  
Dimensioning a Sketch Using the Baseline Option 2-4  
Dimensioning a Sketch Using the Known Option 2-4  
Dimensioning a Sketch Using the Normal Option 1-16

Dimensioning a Sketch Using the Perimeter Option 2-2  
Dimensioning a Sketch Using the Reference Option 2-3  
Dimensioning an Arc 1-19  
Dimensioning Revolved Sections 1-20  
Dimensioning the basic sketcher entities 1-19  
Dimensioning the drawing views 11-2  
Dimensioning the sketch 1-15, 2-2  
DIRECTION submenu 3-8  
Done Refs 7-13  
Drawing a Circle 1-13  
Drawing a Circle Using the 3 Point Option 1-15  
Drawing a Circle Using the 3 Tangent Option 1-14  
Drawing a Circle Using the Center/Point Option 1-13  
Drawing a Circle Using the Concentric Option 1-13  
Drawing a Circle Using the Fillet Option 1-14  
Drawing a Circle Using the Mouse Sketch 1-5  
Drawing a Line 1-6  
Drawing a Line Using the 2 Points Option 1-7  
Drawing a Line Using the 2 Tangent Option 1-8  
Drawing a Line Using the Horizontal Option 1-9  
Drawing a Line Using the Mouse Sketch 1-4  
Drawing a Line Using the Parallel Option 1-7  
Drawing a Line Using the Perpendicular Option 1-7  
Drawing a Line Using the Pnt/Tangent Option 1-8  
Drawing a Line Using the Tangent Option 1-8  
Drawing a Line Using the Vertical Option 1-9  
Drawing a Point 1-5  
Drawing a Rectangle 1-10  
Drawing a Sketch Using the Mouse

- Sketch 1-4
- Drawing an Arc 1-10
- Drawing an Arc Using the 3 Point Option 1-12
- Drawing an Arc Using the 3 Tangent Option 1-11
- Drawing an Arc Using the Center/Ends Option 1-12
- Drawing an Arc Using the Concentric Option 1-11
- Drawing an Arc Using the Fillet Option 1-12
- Drawing an Arc Using the Mouse Sketch 1-5
- Drawing an Arc Using the Tangent End Option 1-11
- drawing display options 1-28
- Dynamic Modification of a Feature 5-17
- E**
- Edge On Srf 9-7
- Edit Rel 8-11
- Editing the Cross Section Hatching 10-17
- Editing the drawing views 10-14
- Editing the features of a model 5-13
- Editing The Geometric Tolerances 11-18
- Entering the Part mode 3-2
- Entering the Sketch Mode 1-2
- Equality Relations 8-9
- Erasing the Drawing View 10-15
- Evaluate 8-11
- Explicit Relationship 3-18
- Extrude 3-3
- Extrude > Thin 3-13
- Extrude Cut 4-20
- F**
- Feature Creation dialog box 3-12
- Feature-Based Nature Of Pro/ENGINEER i
- File menu options viii
- Fix 9-7
- Formed 7-14
- Free Ends 7-5
- From File 7-14, 8-9
- FromDifModel 6-8
- FromDifVers 6-8
- Full & Local 10-10
- Full Section View 10-9
- Full View 10-7
- G**
- General 7-11
- General View 10-5
- Generating the Drawing Views 10-5
- Geom tools 1-24, 2-9
- Geometric Tolerances 11-15
- Geometry Representation 9-15
- GET SELECT submenu 1-27
- GETTING STARTED WITH Pro/ENGINEER 2001 vi
- Graph View 10-6
- Graphics Representation 9-14
- H**
- Half Section View 10-9
- Half View 10-7
- Helical Sweep 8-6
- I**
- Implicit Relationship 3-18
- important terms and definitions vii
- Independent 6-8
- Insert 9-6
- Intent Chain 7-7
- Intr. Surfs 7-14
- L**
- Left Handed 8-7
- Local Section View 10-9
- M**
- Make line or two vertices vertical 1-16
- Managing files in Pro/Engineer xviii
- Master Representation 9-13
- Mate 9-3
- Mate Coincident 9-3
- Mate Offset 9-3
- Mate Oriented 9-4
- Menu Manager xviii
- Merge Ends 7-5
- Mirror 6-7
- Mirroring a geometry 6-8
- Model Tree xix
- Modifying a feature 5-17
- Modifying a sketch 1-20, 2-6
- Modifying and Editing the Dimensions 11-5
- Modifying Dimensions when the Intent Manager is On 1-21
- Modifying other Parameters 10-17
- Modifying the Boundaries of Views 10-16
- Modifying the Components of the Assembly 9-17
- Modifying the Cross Sections 10-16
- Modifying the Dimensions of a Feature of a Component 9-18
- Modifying the Dimensions using the Dimension Properties dialog box 11-6
- Modifying the drawing items using the Shortcut Menu 11-10
- Modifying the Drawing views 10-15
- Modifying the Perspective Views 10-17
- Modifying the Sketched entities 12-3
- Modifying the text 2-17
- Modifying the Values 10-17
- Move 6-7
- Move Tab 9-10
- Moving the Drawing View 10-14
- N**
- Need for datums in modeling 4-2
- New Drawing dialog box options 10-2
- New Refs 6-6
- Norm To Traj 8-7
- Norm To Traj option 8-4
- NrmToOriginTraj Option 8-2
- NrmToOriginTraj option 8-2
- O**
- One By One 7-6
- Open 7-11
- Options aiding the construction of parts 5-2
- Options aiding the construction of parts 5-2
- Other protrusion options 7-2
- P**
- Packaging the Components 9-12
- Parallel 7-8
- Parametric Nature of Pro/ENGINEER v
- Parent child relationship 3-17
- Partial View 10-8
- Pattern 6-2
- Pattern Options 6-3
- Pattern Types 6-2
- Perspective views 10-13
- Pivot Dir option 8-3
- Place Tab 9-8
- PLACEMENT Constraints 9-3
- Pnt On Line 9-7
- Pnt On Srf 9-7
- Pro/ENGINEER i
- Procedure to redefine a feature with elements 5-14
- Procedure to redefine a feature without elements 5-15
- Projected 7-14
- Projection View 10-6
- Q**
- Quit Refs 7-13

**R**

Redefining a Feature of a Component 9-18  
 Redefining Features 5-13  
 Redefining the Components of the Assembly 9-15  
 Regenerating a sketch 1-22  
 Regeneration failed 2-18  
 Remove 7-12  
 Remove All 7-12  
 Reordering 5-15  
 Reordering the Components 9-15  
 Reorienting the Views 10-16  
 Replacing Components 9-16  
 Replacing the Dimensions of a Sketch Using the Rep 2-6  
 Rerouting 5-16  
 resolve sketch Dialog box 2-19  
 Resuming the Drawing Views 10-15  
 Retrieving the user-defined formats in the drawing 12-6  
 Revolve 3-14  
 Revolve > Solid 3-15  
 Revolve > Thin 3-15  
 Revolve Cut 4-20  
 Revolved View 10-6  
 Ribs 5-12  
 Right Handed 8-7  
 Rotational 7-10  
 Rounds 5-8

**S**

Same Refs 6-6  
 Sec tools 2-17  
 Sect to Srfs or Blend Section to Surfaces 8-7  
 Sectional Views 10-8  
 Select Traj 7-4  
 Shell option 7-12  
 Show / Erase dialog box options 11-2  
 Show component in a separate window while specifying constraints 9-8  
 Show component in the assembly window while specifying constraints 9-8  
 Show Rel 8-11  
 Simple and Advanced Rounds 5-8  
 SKET VIEW submenu 3-8  
 Sketch 7-14  
 Sketch Traj 7-2  
 Sketching a trajectory aligned to an existing geometry 7-4  
 Sketching Advanced Geometry 2-12  
 Sketching in the Drawing Mode 12-2  
 Smooth 7-8  
 Sort Rel 8-11  
 SPEC TO or SPEC FROM menu 3-9

Srfs to Srfs or Blend Between Surfaces 8-7

Straight 7-8  
 Suppressing 5-16  
 Suppressing/Resuming the Components 9-16  
 Surf Chain 7-7  
 Sweep 7-2  
 Sweep > Solid 7-2  
 Sweep > Thin 7-7  
 Sweep Cut 7-7  
 Swept Blend 8-4  
 Switch Dim 8-12  
 System Requirements for Pro/ENGINEER 2001 v

**T**

Tangent 9-6  
 Tangent Chain 7-6  
 The Bill Of Material 9-21  
 the default datum planes 3-2  
 The Drawing Mode 10-2  
 The HOLE dialog box 5-2  
 The Sketch Mode 1-2  
 The Sketcher Environment 1-3  
 Thru Axis 8-7  
 Thru Points 7-14  
 Toolbars xx  
 Total Align 10-11  
 Total Unfold 10-12  
 Total Xsec 10-11

**U**

Understanding the Function of the mouse buttons xx  
 Unfold Xsec 10-11  
 User Prog 8-12  
 User-defined drawing formats 12-5  
 Uses of Patterns 6-2  
 Using Blend Vertex 7-11  
 Using Relations 8-9  
 Using Selections dialog box 5-18  
 Using the Assembly Bill Of Material in the Drawing 12-10  
 Using the Sketch Mode 1-2

**V**

Var Sec Swp Option 8-2  
 Variable 8-6

**W**

Working with Constraints 1-16



## List of other Publications by Sham Tickoo and CADCIM Technologies

The following is the list of the other publications by Sham Tickoo and CADCIM Technologies.

### Autodesk Inventor Book (US Edition)

- Autodesk Inventor for Designers, Release 5  
CADCIM Technologies, USA

### Mechanical Desktop Book

- Mechanical Desktop Instructor, Release 5  
McGraw Hill Publishing Company

### AutoCAD Books (US Edition)

- AutoCAD 2002: A Problem-Solving Approach  
Autodesk Press
- AutoCAD LT 2002: A Problem-Solving Approach  
Autodesk Press
- Customizing AutoCAD 2002  
Autodesk Press
- AutoCAD 2000: A Problem Solving Approach  
Autodesk Press
- Customizing AutoCAD 2000  
Autodesk Press
- AutoCAD LT 2000: A Problem-Solving Approach  
Autodesk Press
- Customizing AutoCAD R14  
Autodesk Press
- AutoCAD LT 97: Problem Solving Approach  
Autodesk Press
- AutoCAD Release 13 Update Guide DOS/Windows  
Autodesk Press
- AutoCAD LT 2.0 for Windows: A Problem Solving Approach  
Autodesk Press
- AutoCAD: A Problem Solving Approach DOS R 13 - 3 Hole Punch  
Autodesk Press
- Customizing AutoCAD: Release 13 for DOS and Windows  
Autodesk Press
- AutoCAD: A Problem Solving Approach Release 13/DOS  
Autodesk Press
- Customizing AutoCAD Release 12  
Autodesk Press

### AutoCAD Books (Italian Edition)

- AutoCAD 2000 Fondamenti
- AutoCAD 2000 Tecniche Advantaze

**AutoCAD Book (Chinese Edition)**

- AutoCAD 2000

**AutoCAD Books (Indian Edition)**

- AutoCAD 2002 with Applications  
Tata McGraw Hill Publishers
- Understanding AutoCAD 2002  
Tata McGraw Hill Publishers
- Advanced Techniques in AutoCAD 2002  
Tata McGraw Hill Publishers
- AutoCAD 2000 with Applications  
Galgotia Publishers
- Understanding AutoCAD 2000  
Galgotia Publishers
- Advanced Techniques in AutoCAD 2000  
Galgotia Publishers
- AutoCAD 14 Bible  
Galgotia Publishers
- Understanding AutoCAD 14  
Galgotia Publishers
- Advanced Techniques in AutoCAD 14  
Galgotia Publishers

**3D Studio MAX and VIZ Books**

- Learning 3DS Max: A Tutorial Approach, Release 4  
Goodheart-Willcox Publishers (USA)
- Learning 3D Studio VIZ: A Tutorial Approach  
Goodheart-Willcox Publishers (USA)
- Learning 3D Studio R4: A Tutorial Approach  
Goodheart-Willcox Publishers (USA)
- Learning 3D Studio MAX/VIZ 3.0: A Tutorial Approach  
BPB Publishers (India)